

“70W” is on average power meter.

It is said that it is designed performance.

The ALC of this model works very efficient. So this model transmits “clean” (low distortion) signal.

As a result, the average power meter shows low value.

To measure the output power of SSB, we always recommend to use peak power meter, not average power meter.

Then, you will see almost 100W.